

MD 052B2010



Mounting Instructions

5a M5 4x	5f M6 4x	5k M8x25 4x
5b M6 4x	5g M8 4x	5l M8x35 4x
5c M8 4x	5h M4x20 4x	5m M8 4x
5d M4 4x	5i M5x20 4x	
5e M5 4x	5j M6x25 4x	

2a

2b

1a

1b

3

4

1c

1d

5

6 Optional